This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- (•) BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.




Fig. 1





Fig. 2






Fig. 4a





Fig. 4b

3/14



System and Method of Use Thereof
Nicola John Policicchio et al
Case 7368C3C




Fig. 7






Fig. 7a

Cleaning Composition, Pad, Wipe, Implement, and System and Method of Use Thereof Nicola John Policicchio et al Case 7368C3C












Fig. 9





Fig. 10

System and Method of Use Thereof
Nicola John Policicchio et al
Case 7368C3C

10/14

->- Voltage at Motor Terminal (V) -■- Volumetric Flow rate (ml/s) ->- Spray Nozzle Inlet Pressure (kpa)

Spray Nozzle Inlet Pressure (kpa)



Voltage at Motor Terminal (V)
Volumetric Flow Rate (ml/s)







Fig. 12












Fig. 15